
INSTRUCTIONS



3. Description of monument and accessories set to perpetuate the corner position.

- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography tles, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECORD	ATION
-----------	--------	--------	-------

	ÇERTI	FIED CORNER I	VECOUDAI	IUN	
Co	sw 1/16 sec. 4 orner	TR	F	P.M.M.	County
1.	No previous record.				
II.	No evidence found on the ground.				
III.	. At the determined corner position, se with attached 3 1/4 in. dia., U.S.D.				he ground
	from which				
	A douglas fir, 12 ins. dia., bea A spruce, 14 ins. dia., bears N3				


Built a collar of stone around the monument.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, West, 3 ft.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs

Magnetic Declination: East, 19





SKETC	H OF	COR	NFR

	Lucih		Sec. 4		
Office of Clerk and Recorder, County	of Marie M	This ''corner			
record" was filed for record on	200 8, 1990				
was noted on the cross-index plat and	d is assigned page No.	4291 in	,	-+	
book No.	County C	1 by De Duck		+-	
	D-10	31 N 31 W			

· - corner this sheet Cross Index No. -