CERTIFIED CORNER RECORDATION T. 31 N R. 33 W P.M.M. LINCOLN County C-E 1/16 Corner\_ Found Brass Cap. per Cor. Rec. #496 S85°36'39"E Found Brass Cap, 2645.37 per Cor. Rec. #23 1322.68 1322.68 2639.96 **MONTANA ZONE 2500** S85°31'10"E S04°48'01"W NAD83 (1999) IFT 1322.18 GRID BEARINGS AND DISTANCES Found Aluminum Monument, per Cor. Rec. #3282 S85°25'40"E 2649.56' S85°25'40"E 2643.35 Found Brass Cap. 2645.04 per Cor. Rec. #23 Found Aluminum Monument, per Cor. Rec. #10571, S07°33'51"W 3.24' from C1/2. N85°16'41"W S04°48'01"W 1325.15 **LEGEND** S85°07'41"E Found Aluminum Monument, Found Section Corner As Noted 2651.04 per Cor. Rec. #3281 Found BLM Brass Cap Found Quarter Section Corner As Noted Found Center Quarter Corner As Noted Found 5/8" Rebar, per Cor. Rec. #3284 Set 5/8" Rebar With Aluminum Cap, Stamped "J. SMITH 14739LS" CERTIFICATION certify the information shown herein is true and correct Smith certify that thi veyor & Scal. 74739 14739 LS Robert Peccia & Associates SKETCH OF CORNER LINCOLN Office of Clerk and Recorder, County of This "corner Sec. 32 211712 BOOK: CCR CCER'S PAGE: 11192 Pages: 1 record" was filed for record on STATE OF MONTANA LINCOLN COUNTY was noted on the cross-index pla RECORDED: 05/29/2008 10:16 KOI: CCER'S CLERK AND RECORDER TAMMY D. LAUER TO: ROBERT PECCIA & ASS'S. book No. X-8 T 31 N R 33 W PMM Cross Index No. \_\_

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• corner this sheet