CERTIFIED CORNER RECORDATION T. 31 N R. 33 W P.M.M. LINCOLN County N 1/16 Corner\_ Found Brass Cap S85°36'39"E per Cor. Rec. #496 Found Brass Cap, 2645.37 per Cor. Rec. #23 1322,681 1322.68 2639.96 **MONTANA ZONE 2500** S85°31'10"E S04°48'01"W NAD83 (1999) IFT 1322.18' **GRID BEARINGS AND DISTANCES** 1319.98' Found Aluminum Monument, per Cor. Rec. #3282 S85°25'40"E 2649.56' S85°25'40"Ě 2631.18' 2643.35' Found Brass Cap, per Cor. Rec. #23 Found Aluminum Monument, per Cor. Rec. #10571, S07°33'51"W 3.24' from C<sub>4</sub>. N85°16'41"W 1325.15 **LEGEND** S85°07'41"E Found Aluminum Monument, Found Section Corner As Noted 2651.04 per Cor. Rec. #3281 Found BLM Brass Cap Found Quarter Section Corner As Noted Found Center Quarter Corner As Noted Found 5/8" Rebar, per Cor. Rec. #3284 Set 5/8" Rebar With Aluminum Cap, Stamped "J. SMITH 14739LS" CERTIFICATION <sup>7</sup>4739 SKETCH OF CORNER LINCOLN Office of Clerk and Recorder, County of . This "corner Sec. 32 211716 BOOK: CCR CCGR'S PAGE: 11196 record" was filed STATE OF MONTANA LINCOLN COUNTY was noted on the RECORDED: 05/29/2008 10:19 KOI: CCER'S . in TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 TO: ROBERT PECCIA & ASS'S <u>W-9</u> t. <u>31 N</u> r. <u>33 W</u> <sub>PMM</sub> Cross Index No. \_\_

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet