CERTIFIED CORNER RECORDATION T. 31 N R. 33 W P.M.M. LINCOLN County E 1/16 Found Brass Cap. S85°36'39"E per Cor. Rec. #496 Found Brass Cap, 2645.37 per Cor. Rec. #23 1322.68 1322.68 **MONTANA ZONE 2500** S85°31'10"E NAD83 (1999) IFT 1322.18 **GRID BEARINGS AND DISTANCES** Found Aluminum Monument, per Cor. Rec. #3282 S85°25'40"E 2649.56' S85°25'40"E 2643.35 2631.18 Found Brass Cap. S04°48'01"W 2645.04' per Cor. Rec. #23 Found Aluminum Monument, per Cor. Rec. #10571, S07°33'51"W 3.24' from C1/2. N85°16'41"W 1325.15 **LEGEND** S85°07'41"E Found Aluminum Monument. Found Section Corner As Noted 2651.04 per Cor. Rec. #3281 Found BLM Brass Cap Found Quarter Section Corner As Noted Found Center Quarter Corner As Noted Found 5/8" Rebar, per Cor. Rec. #3284 Set 5/8" Rebar With Aluminum Cap, Stamped "J. SMITH 14739LS" CERTIFICATION ⁷4739 SKETCH OF CORNER LINCOLN . This "corner Office of Clerk and Recorder, County of Sec. 32 record" was filed ? 211717 BOOK: CCR CCER'S PAGE: 11197 Pages: 1 was noted on the RECORDED: 05/29/2008 10:20 KOI: CCER'S _ , in TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 TO: ROBERT PECCIA & ASS'S V-8 T. 31 N R. 33 W PMM Cross Index No. _ Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• corner this sheet