## INSTRUCTIONS

- Description of evidence found, note discrepancies in the record, state method of establishing lost or obtterated
  - Description of monument and accessories set to perpetuate the corner position.
- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography fles, position of accessories, etc.
   Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Filt in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

R. \_34W . Corner SE Corner Sec. 16 County

1. Found: BLM brass capped monument marked as shown below from which,


A 10" Fir bears N 10½°E 53 links scribing partially overgrown. Posted.

A 12" Fir bears S47½°E 8 links scribing partially overgrown. Posted. A 12" Fir bears S 37°W 17 links scribing partially overgrown. Posted. An 11" Fir N 63°W 51 links scribing partially overgrown. Posted. A location poster on a 32" Fir bears N 27°E 17½ links. Painted monument and accessories with bright red paint.

MN R341

book No.

Found B.L.M. standard brass capped monument marked as shown.



N-13

Cross Index No.

T. 31N R. 34W PMM

· corner this sheet