INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.

- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
 Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>C-S-SW 1/64 Corner Sec. 17</u> T. 31N R. 34W P.M.M. Lincoln

- 1. This corner not previously set.
- Ser: A 3" X 30" aluminum capped monument marked as shown below from which, A 10" Spruce bears N $52^{\circ}E$ 12.6 feet scribed C-S-SW 1/64 S17B.T. and posted. A 7" Cedar bear S 37°E 14.8 feet scribed C-S-SW 1/64S17B.T. and posted. A location poster on a 3" Alder which bears N 72°E 4.6 feet. Paint monument and accessories with bright red paint.



Set 3" aluminum monument marked as shown.

SET AN ALUMINUM MONUMENT 3"X 30" MARKED AS SHOWN. M72°E A.GFT. M72°E A.GFT. T"CEDAR	CERTIFICATION Jack H. Ninneman Certify the information shown herein is true and dorrect. Jack H. Ninneman Signature Ground Purly Chief Jack H. Ninneman Certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) Judy H. Ninneman Signature of Surveyor & Secil Oct. 82 A661S Date: Reg. No.
SKETCH OF CORNER	Emphyer: Ninneman Engineering Inc.
Positive of Clerk and Recorder, County of	etty L. Conces lat deputy
Cross Index No. Min-6 T.	31N R. 34W PMM • - corner this sheet