INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing just or obliterated corners.
- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner E-E-E 1/256 Corner Sec.17 T. 31N R. 34W P.M.M. Lincoln Coun
--

- This corner not previously set.
- Set: A 3"x30" aluminum capped monument marked as shown below from which, A 14" Fir bears N4^OW 31.5 feet scribed E-E-E 1/256 S 17 B T and posted. An 18" Fir bears S6^OE 37.1 feet scribed E-E-E 1/256 S 20 B T and posted. A location poster on a 3" Fir bears N $82^{\circ}W$ 14.0 feet. Painted monument and accessories with bright red paint.



Set 3" aluminum monument marked a. 1982 HAN Aldo'S	s shown.
ALCCATION POSTER AN AS "FIR WAICH BEARS N 82" W 14.0 FT. N 82" MARKED AS SHOWN. SKETCH OF CORNER	CERTIFICATION 1. Jack H. Ninneman certify the Information shown herein is true and correct. Signature Ground Party Chief 1. Jack H. Ninneman certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: Oct.82 Reg. No. 4661S Employer: Ninneman Engineering Inc.
Office of Clerk and Recorder, County of LINCOLN record" was filed for record on the Dec. 9 was noted on the cross-index plat and is assigned page No. 2/ book No	Betty L. Conces