

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography etc., position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner E 1/16 S 10 T. 33N R. 26W PMM Lincoln County



There is no previous record of this corner having been set.

Set a $2\frac{1}{2}$ in. Brass Tablet in a boulder one foot below the surface of a logging road.

From which

A 10" Fir bears $N44^{\circ}W$, 29.95 ft. scribed "E 1/16 S 10 BT"

A 9" Fir bears $S74^{\circ}W$, 17.70 ft. scribed "E 1/16 S 10 BT"



SKETCH OF CORNER

CERTIFICATION
I, Murry Graham III, certify the information shown herein is true and correct.

Murry Graham III
Signature of Surveyor & Seal

S.R. Smith
Signature of Surveyor & Seal

I certify that this corner Record correctly represents work performed by me, or under my direction in compliance with the Corner Recordation Act (50-22-101, et seq., M.D.A.)

S.R. Smith
Signature of Surveyor & Seal

Date _____ Reg. No. 47405

Employer SMITH SURVEYING CO.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 29th day of 1982. was noted on the cross-index plat and is assigned page No. 1733, in book No. _____

Eleanor L. Vaughn by Betty L. Conces
County Official deputy

Cross Index No. E-16 T. 33N R. 26W PMM

