INSTRUCTIONS

. Original and/or subsequent record used to evaluate the corner position

Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ties, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner CN 16 Sec 27 T. 33N R. 26W P.M.M. Lincoln County

There is no previous record of this corner having been set.


Set a 2 in x 30 in. Aluminium Pipe with a 32 in diameter Aluminium cap stamped as shown and raised a collar of stone.

From which

A7" Tam. bears 522°W, 5.80 ft.

A 20 Tam. bears N30W , 44.70 ft.

Both B.T.'s are scribed "CN 16 BT"



CERTIFICATION

I. MUSTY Gro. ham

Certify the information shown herein is true and correct.

Signature Ground Party Chief

I. S. MITH

Certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70.22-10), et seg., M.D.A.)

Signature of Surveyor & Seal

Date: 19 82 Reg. No. 47405

Employer: SMITH SURVEYING CO.

Office of Clerk and Recorder, County of	Lincoln . This "corner					
record" was filed for record on the	July 28th day of 1989					
was noted on the cross-index plat and is assigned page No, in						
book No.	Eleanor L. Vaughn by Betty L. Conces County Official aeputy					
	county official deputy cross Index No. 5-15 33N R 26W PMM					

• - corner this sheet

The second secon		THE THE PART OF TH	Terretan nat	A Charles &
The same of the sa				
		Character and the state of the		
	tions 26, 27, 8,35	733N R26	W	77.
7/N69:58 E 769/33 C	(E) Alur (2)		BUN NB9.5158	"E 2639.23 1 64
NBY: 58 05 F 2647.	33		/3/9.62	/3/9.6/
			200	7
2 C	(C) 00		0 N89'53'47	The second second
NBVS0S0E 2647	\$8 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		5	22.0
	7		8	5289-12
NB9:5535/E	5297.36	1321.10' /321.	/323.5/	
33.44 322	41.66.0)	639.57	3/8.74	1319.7
	32.00	N89°52'51".E 264	2.16' N89'581	6° € 2646.98
1322.82 132.	82 7	1321.08' 1321.	08 7323.49	
8 6 7 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	0.07 0.07 0.08	1320.	18/8/	13/9
777.0	3/15 644.31 en M89°49'54'E 2653.50'		07 Jum /323.47	1323-46 02'E 2646'93'
(N8) SS & 2645	94- GLO) (N84.22 E 26.42.44 CTO)		94.03	
	0,000	N89'5'159'E 26'	40.61	
	3	320.30 3 /32	0.31	96
	00.00	321.72	333	000
			9.54'	647.03' 5286.10'
		7,07,07	3 5	
	A Company of the Comp		£ 78	
	Down Pierry Down		22.20	
	Se See		0.0%	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
C69:4820E 2635	70-64-0)	The second secon	847	
			3. 中国 200 0年	
			And the state of t	
	Section 19 and 1	The second secon	and market the state of the	1424
		THE PARTY OF THE P		San Section
		The state of the s		111
			4 - 4	
	The Laboratory of the Control of the		A Branch	and the state of t
	[1]			