I. Uriginal and or subsequent record used to evaluate the 2. Description of evid 3. Description of the union and accessuries set to perpetuate the corner position 6. Shotch or corner, show all pertinent data which can best be shown in a six topography tire, position of accessories, etc. 5. Certification must be signed and seeled by Registered Land burveyor in State of Montana.

5. Fill in Cross Index & Section Diagram at bottom of abset. **CERTIFIED CORNER RECORDATION** N 1/16 Cor. Sec. 14 T. 33N R. 26W P.M.M. LINCOLN _County No record or evidence of corner being previously set. I position corner from found Section and Quarter corners and as shown on the Certificate of Survey as filed and as of record in the Lincoln Co. Courthouse. I set a 3" alum. cap for corner position, from which: A 12" fir bears N.7°E., 56.4° scribed N 1/16 S13 BT A 9" fir bears N.58°W., 21.1° scribed N 1/16 S14 BT Painted red bands around BT's and painted blazes red. Posted BT, Attention, and Location signs.
Placed a 6' metal post w/survey monument sticker along side cap. 12" FIR CERTIFICATION GLENN KNODLE 4" FIR Knoolle certify that this Corner Record correctly represents work performed by me or under by direction in compilance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) Gene Warre Date: 10/84 Reg. No. 27345 Employer: ROCKY HOUNTAIN SURVEYORS SKETCH OF CORNER Office of Clerk and Recorder, County of LINCOLN _ . This "corner _ day of 19*5*⊀ was noted on the cross-index plat and is assigned page No. . County Others K21 т. 33N н. 264 рмм · corner this sheet

book No. .