		1 9 BOOK: CCR CCER'S PAGE: 10764 Tes: 1 STATE MONTANA LINCOLN COUNTY
		RECORDED: 02/02/2005 8:34 KOT: CCER'S
		CORAL M. CUMMINGS CLERK AND RECORDER FEE: \$0.00 BY: TO: FILED ,
		CERTIFIED CORNER RECORDATION
	CornerC.O.E A	19 S22 T. 32 N. R. 29 W. P.M.M. LINCOLN County
I.	Record: <u>1893 Original G</u> and Walter G. Filer	L.O. Subdivision and Meanders of Township 32 North. Range 29 West. by Paul S. A. Bickel
	1972 U.S. Army Corp of 8 of 37; Standard U.S	Engineers Libby Dam—Lake Koocnausa Cadastral Project. District File No. E 53—1—154. Sheet .C.E. Concrete Monument
II.	Found: A U.S.C.E. 3 1/2 marked as shown.	2 in. diam. brass disk set in a 4 in. x 4 in. concrete post, 6 ins. above ground with disk PROJERO A 19 YEAR 1973
III.	Established two new bed	pring trees:
	A pine, 8 ins. diar A pine, 9 ins. diar	m., bears N86°E, 4.8 ft., mkd. A—19 BT. m., bears N32°W, 27.7 ft., mkd. A—19 BT.
	Painted the scribed face Bearing Tree signs.	es red and a 6 in. red band around bearing trees and attached Land Survey Monument and
	Date of Fieldwork: 9/29 Survey crew: Steve Boy Magnetic declination: 18	er, Tom Hommel
		compass and loggers tape pervisions Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211
		CERTIFICATION Steven A. Boyer 9750LS certify the information shows herein is true and correct. Signature Ground Party Chief Roger O. Green certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (71/2-101, et seq., M.C.A.) N86°E A.8 ft. A.8 ft.
CIVE	TOU OF CORNER	Dote: <u>9/29/2004</u> Reg. No. <u>13769LS</u> NOT TO SCALE Employer: U. S. Forest Service
SKE	TCH OF CORNER	Lincoln Sec. 22
	Office of Clerk and Reco record" was filled for re- was noted on the cross book No.	This "corner 182239 BOOK: CCR CCER'S PAGE: 10764 Pages: 1 STATE OF MONTANA LINCOLN COUNTY RECORDED: 02/02/2005 8:34 KOI: CCER'S CORAL M. CUMMINGS CLERK AND RECORDER FEE: \$0.00 BY: AND RECORDER TO: FILED , A-19 Cross Index No. C.O.E A-19 T. 32N.R. 29W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet