1	ERTIFIED	CORNE	R RECOR	DATION	
Corner9 10	Т.	32 N.	R. 29 W.	P.M.M. Lincoln	County
RECORD - 1902 GLO SURVEY SET A TRACHITE STONE 22 X 9 X WHICH A 14 INS. DIAM. TAMARAC A 14 INS. DIAM. FIR MARKE FOUND ADJACENT CORNERS AS SHOWN	< MARKED '1/4 S D '1/4 S 9 BT' BE	10 BT' BEARS	S69°45'E 24 LKS		ı ´
<u>ET</u> 5/8" REBAR WITH PLASTIC CAP N	iarked 'Marqi	JARDT 7328 S '	FROM TIES TO	ADJACENT CORNERS.	
Not to Scale Basis of bearings: South	2649.58° 2649.58° 2649.58°	 -			
line of Section 10 taken as N89°56'W per original GLO survey.	N00°02'36"E		ND DECREPIT CA INE, ±105'	BIN	
ESTABLISHED NEW BEARING TREE 10" DIAMETER FIR. BLAZED FACE	4'E 59 510 ⁷	.45'E	ER BY SINGLE PR ESTABLISHED NE " DIAMETER FIR	W BEARING TREE	
	N00'02'36"E 2649.58'		I. ce	Brian Parnell rity the information shown herein	
FOUND REMAIN: ORIGINAL COR (TAMARACK STU	NER 310 313 MP)	-	Da	Dawn Marquardt rify that this Corner Record correctioned by me or under my direction and the Corner Recordation and the Corner Recordation and the Reg. No. 7 Marquardt & Ma	MARQUARIDT 7328 LS
Office of Clerk and Recorder, record" was filed for recor so was noted on the cross-in	200608 BOOK: ATE OF MONTANA CORDED: 01/29/ MMY D. LAUER	incoln CCR CCER'S LINCOLN COUN 2007 9:24 N	. This PAGE: 1099 YTY KOI: CCER'S	"corner	Sec. 10
BOOK NO.	E: \$0.00 : MARQUARDT SURVI	EYING, INC. 28	5 1ST. AVE. E.E.,	KALISPELL,	

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors