- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner NE-SE-NW/256,510 T. 3ZN R. 3/W P.M.M. LINCOLN

- 1) NO ORIGINAL EVIDENCE / RECORD.
- 2) NONE.
- 3) SET 3½" ALUMINUM CAP ON 3/4" ROD FROM WHICH.

STEEL FOST BEARS NELY II TEET.

MOUND. -WESTSH. OF RD (SPIKE) SPIKES ALONG WEST EDGE ROAD Sio NE-SE-NW BUNTONS TECH SUS., FUC. **SKETCH OF CORNER** Office of Clerk and Recorder, County of record" was filed for record on Sypt 10, 1985 was noted on the cross-index plat and is assigned page No. Sugel by County Official book No.

COR. FALLS IN HAY FIELD NO BITS AVAILABLE

· - corner this sheet