2. Description of evidence found, note discrepa

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- topography use, position as accessories, etc.

 5. Certification must be signed and sealed by Registered Land St

 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

SOUTH /4 CORNER SEC. 16 T. 34 N R. 25 W PMM LINCOLN County NORTH Y4 CORNER SEC. 21

ORIGINAL RECORD:

SET POST 3' LONG, 3" SQUARE, 24" IN GROUND

MARKED "1-45 ON NORTH" FACE, FROM WHICH


A FIR, 10" DIA , BEARS 5 20 30 E. 19 LKS. DIST., MARKED 1-45. B.T.

A SPRICE B"DIA, BEARS N. 40°30'W. 26 LKS. DIST., MARKED 1-45.B.T.

NOTHING FOUND:

book No./.

SET ALUMINUM CAP BY SINGLE PROPORTION SEE C. OF S. NO. 992 FOR ADJACENT CORNERS



Eleanor L. Vaughn by County Official

_ т. <u>34И r. 25 W</u>pmm ·

corner this sheet

THE MAINT CAP BY CINGLE FIGHT TON ALL TON SEE TO ALL THE TON SEE TO ALL TON SEE TO ALL TON ALL

E Strangen and Comments

.

. ...

,