4. Sketch or corner, show all pertinent date

wries, ytc. 5. Certification must be signed and sealed by Registered Las 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner C-W-E 1/64 Sec. 31 . T. <u>34N</u> R. <u>25W</u> __ P.M.M. LINCOLN


No record or evidence of corner being previously set.

I position corner from found section and quarter corners and as shown on the Certificate of Survey as filed and as of record in the Lincoln Co. Courthouse.

I set a 3" alum. cap for corner position, from which:

A 13" pine bears S.67°30°E., 27.9° scribed C-W-E 1/64 S31 BT A 15" pine bears S.14°E., 62.3° scribed C-W-E 1/64 S31 BT

Painted red bands around BT's and painted blazes red. Posted BT, Attention, and Location signs. 6' metal post w/survey monument sticker along side cap



Office of Clerk and Recorder, County of <u>LINCOLN</u> record' was flied for record on the <u>Nov</u> 30	This "corner Sec. 31
SKETCH OF CORNER	CERTIFICATION 1. GLEMN KNODLE certify the information shown herein is true and correct. Well Knowled Signature Ground Party Chief 1. 4. GENE WARPEN certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) ### Mone Walley Signature of Surveyor & Seal Date: 10/84 Reg. No. 27345 Employer: Rocky Mountain Surveyors

Sugel by County Official

T. 34N H. 25W PMM

corner this sheet

book No.

