INSTRUCTIONS.

Original and/or subsequent record used to evaluate the corner of

scription of evidence found, note discrepancies in the record, state method of establishing jost or obliterati

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ites, position of accessories, etc.
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
 Fitt in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. 34N Corner C & corner Sec.

- (1) This corner not previously set.
- (3) Set 3½" aluminum cap on 30" aluminum pipe stamped as shown below from which:
 A 10 in. Doug fir (scribed C½ S3 BT) bears N 180E 75.2 ft.
 A 12 in. Larch (Scribed C½ S3 BT) bears N 480E 40.2 ft.

A location poster on a le in. D.Fir bears N. 59°E 29.4 ft. Painted monument and accessories with bright red paint.

Set S 3 1983 10."D: File (c/4 5 3 - BT) CERTIFICATION David Stanley Jack H. Ninneman certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Recordation Act" (70-22-101, et seq., M.D.A.) Signature of Surveyor & Seal . /8/83 Reg. No. 4661s Ninneman Engineering Inc. **SKETCH OF CORNER** Office of Clerk and Recorder, County of Lincoln _day of 1984, was noted on the cross-index plat and is assigned page No. . anet B.F. Sugel by Paren R. Kan County Official deputy book No. - corner this sheet Cross Index No.

A Company of the comp (-)

3110 11.0 S. W. 2703 S.