		CERTIFIE	D CO	RNER RE	CORDATION	
Corner .	CE1/16	Sec 7	T35	N. R2	7 W. P.M.M. L	INCOLN County
the esta	NE 1/4 of so blished and s	ection 7 and cre	eates th h a 5/8	ree new pard 3 in. diam. x	larquardt, Reg. No. cels. The position 24 ins. long rebar	for the CE 1/16 wa
II. Foun	d a 5/8 in.	diam. rebar wit	h a yello	ow plastic ca	p marked "MARQUA	ARDT 7328S"
	Accepted the Marquardt rebar as the true position for the CE 1/16. Replaced the yellow plastic cap with a 3 1/4 in. diam. aluminum cap marked as shown.					
				T35N E 1, C—* S3 1376	/16 ⊢C 7	
From	n which the	new bearing tree	es:	200	02	
	A fir, 7 ins. diam., N65°W, 34.8 ft., marked CE 1/16 S7 BT. A spruce, 11 ins. diam., N36°W , 32.8 ft., marked CE 1/16 S7 BT.					
Land	Set a 6 ft. galvanized steel guard post 3.0 ft. north and west, with Property Boundary and Land Survey Monument decals attached. Attached Bearing Tree and Land Survey Monumen signs to the bearing trees. Painted red bands around the bearing trees.					
Date	of Fieldwork	c: 8/12/2002				
Surv Magr Equi	ey crew: Ste netic declinat pment used:	ve Boyer, Tom l tion: 20° East a Hand compass	ssumed and log		W1 1555 AT 50	007 (400) 007 00
0.5.	Forest Servi	ce, Supervisiors	Office,	IIUI HWY. Z	CER	923 (406) 293-62
		765 W. 34.8 M.			Signature Roger O. Greening that this corner is performed by me or und the "corner Recordation".	Ridord currectly represents work or you circetten to committee work and the committee work of the committee wo
KETCH OF	CORNER			NOT TO SCALE	Employer: U. S. Fo	rest Service
Office of	Clerk and Recor	der, County of	Lincoln	This	*corner	Sec. 7
record" w	as filed for reco	ord on	30,	203 10	<u></u>	
was noted book No.	d on the cross-	index plat and is a	ssigned po	age No. Tum	UOI, in	
		<u></u>	C	ounty Official	mund x 20 DB	

Cross Index No. <u>G-04</u> T. <u>35N. R. 27W.</u> P.M., MT · corner, this sheet

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors