Original and/or sul
 Description of evide found, note discrepancies in the record, state method of estat

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and scaled b

topography test, position of accessories, etc.

S. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner C - S 1/16 Section 10 T. 35 N. R. 27 W. P.M.M. Lincoln

There is no survey or corner recordation on file for this corner.

There was no evidence of a monumented corner found.

CORNER PERPETUATION

At the corner point: Set a 3/4" x 30" aluminum rod with a 3 1/4" diameter aluminum cap, approx. 26" in the ground, marked:




from which bearing trees:

fir, 8 ins. in dia., bears S 24° E, 11.1 ft. dist., mkd. CS 1/16 S10 BT.

A larch, 9 ins. in dia., bears S 50° W, 25.1 ft. dist., mkd. CS 1/16 S10 BT.

Set a galvanized steel post with a survey marker decal and a property boundary decal 3ft. East of the aluminum cap.

Painted red bands around the bearing trees and painted the scribing. Attached bearing tree signs and attached Survey Monument ŝigns.



ī						
certify	the informa	tion show	n hereii	i is true ar	id correct	
	S	ignature	Ground	Party Chi	ef	
1.	Phili	рA.	He ly	S		
certify	that this Cor	ner Recor	d correc	tly represe	ents work	performed
by me	or under	y directi	long in o	compliance		
Record	lation Act" (70-22-101	esseq.	M.D.A		
		Tell	A			
		Signature	of Surv	eyor & Sea	al	
Date:_	11:/87	Reg. N	io	4739	<u>s</u>	
; Emplo	yer: F δ	H La	ind S	urvey	ring,	Whitefish

CERTIFICATION

Declination 200 E. SKETCH OF CORNER

	Sec.	10	
Office of Clerk and Recorder, County of <u>Lincoln</u> . This "corner	500.		
record" was filed for record on the		\vdash	
was noted on the cross-index plat and is assigned page No, in			
book No fant bt Sugal by Six Brackoff	<u> </u>	⊢ →	
County Official Day.		 1	
$C_{\text{res Index No.}} = \frac{\text{H} - 15}{\text{T.}} = \frac{35 \text{ N}_{\text{R.}} 27 \text{ W}}{\text{PMM}}$	• · co	rner t	his s

· - corner this sheet