INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, lopography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>No</u>	. 5 HES. 450	·	T. <u>35N</u>	R. <u>32w</u>	P.M.M	Lincoln	County
1.	Record: Small in the ground corner point,	, marked 5	HES 450 on	under a quart N. face and a	zite 24 X 1 a cross (X)	ll X 5 inches, on top for ex	14 inches act
	À cross distance	(X) on a La	rch tree, 1	l inches diam	eter bears	N63 ⁰ 35'W., 35	links

A cross (X) on a Larch tree, 11 inches diameter bears N51 31'E distance; each blazed and scribed 5 HES 450 BT.

Raise a mound of earth 4 feet base, 2 feet high North of corner.

- 2. Found: original stone 6" X 8" X 16" marked 5 HES 450 on West face, cross (X) on top from which a 24" Larch bears S62^O30'E 23.5 feet (posted by others)
 - A 16" Larch bears S61°W 6.0 feet (posted by others)
 - A Larch stump (scribing visible) bears N55°E 6.0 feet posted by others.

