		CERTIFIED CORNE	R RECOR	DATION
0	CW Sec	7 T. <u>35N</u> R.		
Corner	CH SEC	/ 1, R.		M.MCounty
				;
- ,				
Found: A 5/8 in	ns rehar with	vellow plastic can by LS	S 13102 Begr	rs S79°W, .75 ft out of correct
				/4 was found this survey.
Set:				
	Aluminum Mo	nument, 3¼ ins. in diam	., on 5/8 ins.	diam. rebar,
mkd. as	shown;		,	
		. in diam., bears N81'E, 1 iam., bears S52'E, 22.8 f		scribed "CW 1/16 S7 BT";
Steel po	sts with deco	ils, bear North, 2.5 ft. di	st. and East,	2.0 ft. dist.
				•
•				
				1
				OF ACO
				GRASH RZS
				Si CW 1/16 M
				si
				LS9748 2010
				CORECT SERVICE
MAGNETIC I	DECLINATION -	15'4' EAST		
Λ	Stl Post			CERTIFICATION
	North, 2	2.0° 11E, 18.2' (3) 15" D Fir	L _ cer	Erich Shrack rtlfy the formation strong have been been been been been been been be
M		Stl Post	·	
A		East, 2.0'	l, .	LAWRENCE A CLAHE
	872 r		cer per the	rify that this Commitment in the manual manual with formed by the crimder my structur in compliques with a "Comer Regulation Act" (198-22-10), at add (IC.A.)
	15			97.48 LS
	•	ያ-\- 14" Larch - ጀሜ	2	11-10-10 9748 LS
CVETOU	AF 000NF0	ua -	Dat Em	CLAHE & ASSOCIATE
	OF CORNER		· · · · · · · · · · · · · · · · · · ·	
Office of Cler	rk and Recorder,	County of <u>Lincoln</u>		**
record" was	filed for record	229648 BOOK: CCR CCER STATE OF MONTANA LINCOLN C		1632 Pages: 1 Sec. 7
was noted or	n the cross-ind	RECORDED: 11/15/2010 1:27	KOI: CCER'S	,
book No		TAMMY D. LAUER CLERK AND	RECORDER	wind not
		TO: GLARE & ASSOC., INC. P.O.	BOX 1863, SANDPO	IHT, ID. 93860,
		그렇게 하다 가다 가 하는 바로 바로 뜨겁다.		

Cross Index No. G-2 T 35N R 25W PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet