INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Center 1/4 Sec. 30 T. 35 N. R. . 25 W. P.M.M. Lincoln County

Established by Subdivision of Section

Found old post with FS tag North about one foot from the position of the corner I set.

Position falls about 7 ffet south of a fence corner and on line East & West with a North South Fence.

Set 3" x 30" aluminum post & cap.

6 Aspen S. 80° E. 17.5 feet

5" Aspen N. 30° W. 7.5 feet

Bearing tree tags affixed

Brass tags set at base of BTs at root crown distance from corner.

See record of Survey 944

T 35N R25W

2968 \$

..... الموقيد والمرازولات

i i		Onton	D10 . W. 4		
K)		CERTI	FICATION		
1.	_ Milto	n I.	Booth		
certify	the informatio	n shown I	nerein is tro	e and correct	
	Sig	nature Gr	ound Party	Chief	
I,				 	
certify:	or under by	r Record o	orrectly re	presents work lance with the	perforn
	ation Act" (70				, con
7	rella	2	79	ooth	
	Sig	nature of	Surveyor &	k Seal	
Date: .	8/24/81	Reg No.	2968	\$	
		_			
Employ	_{ver:} Se	11.			
	~~~~				

	1981	Date: 8/24/81 Reg. N	2968 S	
The state of the s	SKETCH OF CORNER	Employer: Self		
Office of Clerk	and Recorder, County of Juncoln	This "corner	Sec. €3€	
record" was file	ed for record on the	day of 19 ,	<u> </u>	
was noted on th	e cross-index plat and is assigned page No	1178 in		
book No	Lessent Vando	a his best hill		
	County Of	ficial executy		
	Cross Index No. T-3	T. 35 N R 25 W PMM	• corner th	

