INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner	C-W 1/16	Sec. 30	T. <u>35 N</u>	R <u>25</u>	<u>W</u> P.M.M	Lincoln_	County
--------	----------	---------	----------------	-------------	----------------	----------	--------

Established by Subdivision of Section

See certificate of Survey 944 in Lincoln County Records

Set 3" x 30" Aluminum post & cap

28 Larch (school marm) S. 79° E 32.3 feet Mkd CW 1/16 BT

11 Aspen S. 80 W. 54.9 feet Mkd. C-W 1/16 BT

Bearing tree tags affixed

. 75

Brass tags set at base of BTs at root crown distance from corner.

CERTIFICATION Milton I. Booth T35N R25W certify the information shown herein is true and correct. S 30 CW 1/16 Signature Ground Party Chief certify that this Corner Record correctly represents work performed Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal 2968 \$ 1981 Date: 8/24/81 Reg. No. 2968 S Self

SKETCH OF CORNER	Employer:
Office of Clerk and Recorder, County of	Sec. 30
	. This corner
record" was filed for record on the	day of 198/,
was noted on the cross-index plat and is assigned page	No. 1179 in
book No blaces of.	Vanaly but heter bell.
C	ountly Official alignaty
Cross Index No.	- 2 T. 35 N R. 25 W PMM • - corner this shee
	- Corner trits stiet

