Sketch or corner, show all pertinent data which can best be shown in a sketch extopography ties, position of accessories, etc.
Certification must be signed and sealed by Registered Land Surveyor in State of Mon 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>CN 1/16 S6</u>

P.M.M. Lincoln

County

RECORD: No previous record of corner monumentation on file.

FOUND:


Nothing to show evidence of a previously monumented corner.


A $3\frac{\pi}{4}$ " diam, aluminum cap on a 30" long, $89^{\circ}548^{\circ}$ diam, aluminum rod approx. 28" in the ground, surrounded by a mound of stone and marked as shown.

from which

A fir, 10" diam., bears \$.03°W., 18.2 feet dist., scribed " \$6 BT".

A fir, 10" diam., bears N.89°E., 7.0 feet dist., scribed "X BT".





SKETCH OF CORNER

CERTIFICATION Reed <u>James</u> W. Thomas C. Hill certify that this Corner Record correctly represents work performs by me or under by direction in compliance Recordation Acy (70-22-101, et seq., M.D.A.) 6/23/83_{Reg. No.} 5612 S

Employer: U.S.F.S.

Office of Clerk and Recorder, County of Lincoln		This ''corner	Sec. 6		
record" was filed for record on the	A 1	day of 19 ² ?			
was noted on the cross-index plat and is assigned page No, in				-+-	<u> </u>
book No.	County Of	Betty L. Conces	-		<u> </u>
	County G	meiai o cerpucia		l i	i

R. 26

· - corner this sheet

. . . **∵**