#### INSTRUCTIONS

- Description of monument and accessories set to perpetuate the corner position.
   Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.

# CERTIFIED CORNER RECORDATION

Corner S.E. 1/16 Section 27 T. 35 N. R. 26 W. P.M.M. Lincoln County

# **RECORD:**

Unrecorded Donald V. King Jr. (M.L.S. No. 5212-S) survey done in area.

### FOUND:

A 5/8 inch diam. rebar and P.V.C. cap stamped: KING 5212-S purported to be S.E. 1/16 corner out of position.

## MAINTENANCE:

Set a 5/8 inch diam., 24 inch long rebar with yellow P.V.C. cap stamped: KED 4975-S for S.E. 1/16 corner.


We established two reference points described as follows:

A 5/8 inch diam. rebar 24 inchs long 2 inches above the ground bears N.28°E., 16.70 feet.

A 5/8 inch diam. rebar 24 inched long 2 inches above the ground bears N.52°45'W., 13.32 feet.

Attached BT signs on 4 foot steel posts behind reference points.

book No.



Cross Index No. -

County Official

corner this sheet