INSTRUCTIONS	

- 3. Description of monument and accessories set to perpetuate the corner position.
 4. Sketch or corner, show all pertinent data which can best be shown in a sketch e topography ties, position of accessories, etc.
 5. Certification must be signed and sesied by Registered Land Surveyor in State of Mo
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner W 1/16 Sec. 23

36N

R. 26W

Lincoln P.M.M.,

County

RECORD: None available.


SET:


A 2½" x 30" Forest Service aluminum pipe approximately 30" in ground


with an aluminum cap marked as shown.

FROM WHICH:

An 8" fir bears N80E, 27.6 feet, inscribed 1/16 BT. A 20" fir bears NO4W, 31.2 feet, inscribed 1/16BT.







CERTIFICATION


certify that this Corner Record correctly represents work performed

Date: 1-27-82 Reg. No. 5612-5 USF5

SKETCH OF CORNER

Office of Clerk and Recorder, County of LINCOLN . This "corner record" was filed for record on the ___MARCH day of 19 82 was noted on the cross-index plat and is assigned page No. _ laugh by book No. 🕹

County Official deputy Cross Index No. N ~ 18 T. 36N R 26W PMM



corner this sheet