- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montans.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner CW 1/16 Sec. 14 R. 26W P.M.M. Lincoln County


RECORD: None available.

SET: A 2½" x 30" Forest Service aluminum pipe approximately 26" in ground

with an aluminum cap marked as shown with a stone collar.

FROM WHICH:

An 8" Tarch bears S19W, 10.6 feet, inscribed CW 1/16 BT. An 8" fir bears N87E, 35.9 feet, inscribed 1/16 BT.





	5612 S SURVE MINIMUM SURVE MINIMUM
N 87°E SETCH OF CORNER	CERTIFICATION I. AMES W. REED certify the information shown herein is true and correct. Signature Ground Party Chief I. certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" 170-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: -Z7-8Z Reg. No. 56/2-5 Employer: USF 5
was noted on the cross-index plat and is assigned page No	ry Bettyl. Conces