INSTRUCTIONS

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sixetch or corner, show all pertinent data which can best be shown in a sketch et topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Mot 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner CE 1/16 Cor. Sec. 23 T. 36N R. <u>26W</u> P.M.M. Lincoln County

Record: None available

Set: By section subdivision a standard Forest Service $2\frac{1}{2} \times 30$ inch

aluminum monument with a 3 inch aluminum cap stamped as shown:

From Which: A 12 inch pine bears S86E, 14.9 feet, marked CE 1/16 B.T. A 10 inch pine bears S37W, 16.8 feet, marked XB.T. A location poster bears S43E, 4.8 feet



	MAN NTAN
	THOMAS C HILL 5612 S SURVE
SKETCH OF CORNER	CERTIFICATION IA M E
office of Clerk and Recorder, County of Lincoln record" was filed for record on the Warch 16 was noted on the cross-index plat and is assigned page No book No	Sec. 23 This "corner day of 1989 1035, in by Betty & Conces Official deputy T. 36N R. 26W PMM • corner this sheet

• - corner this sheet