## INSTRUCTIONS

uent record used to evaluate the corner position, e found, note discrepancies in the record, state method of establis

Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner. how all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner . County

RECORD: No record of corner on file.

FOUND: Nothing to show evidence of a previously monumented corner.


SET: A 3½ in. diam. aluminum cap on a 30 in. long by 3/4 in. diam. aluminum rod

approx. 4 ins. above ground, surrounded by stone collar and mkd. as shown.

from which

A spruce, 10 ins. diam., bears N.72°W., 6.1 feet dist., scribed "S35 BT".

A spruce, 12 ins. diam., bears N.85°E., 27.2 feet dist., scribed "S35 BT"





10" SPRUCE

ı. James					•
certify the haform	ation show	n herein	la Irue	and correc	i.

Thomas C. Hill

certify that this Corner Record correctly represents work performed er by direction in compliance 1" (70/22)101, et seq., M.D.A.)

Sec.

Date 10/20/83 Reg. No. 5612S

**SKETCH OF CORNER** 

Office of Clerk and Recorder, County of . Lincoln . This "corner record" was filed for record on the \_\_\_\_\_November  $_{-}$  day of 19 $\chi_{3}$ was noted on the cross-index plat and is assigned page No. 2380book No.

Cross Index No. .

bret & Sizel by Betty L. Conces, deputy
County Official т. <u>36</u> R. 26

· corner this sheet

34