

## INSTRUCTIONS

1. Original and/or subse record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## - CERTIFIED CORNER RECORDATION

Corner 1/4 corner between Sec. 9 & 16 T. 36N R. 27W P.M.M. Lincoln County


Record:

Set a limestone 20x6x4 ins. 15 ins in the ground from which  
 a fir 6" diam. bears N. 25° W. 191 ks.  
 a fir 12" diam. bears S. 10° E 731 ks.

Found stone (no marking) at fence corner. Accepted as corner.

Set Aluminum Cap

See C of S. 10 669 for adjacent corners.



## SKETCH OF CORNER

## CERTIFICATION

I, \_\_\_\_\_  
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt  
 certify that this Corner Record correctly represents work performed  
 by me or under by direction in compliance with the "Corner  
 Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 7-9-81 Reg. No. 2089ES


Employer: \_\_\_\_\_

Office of Clerk and Recorder, County of Lincoln. This "corner  
 record" was filed for record on the July 17<sup>th</sup> day of 1981,  
 was noted on the cross-index plat and is assigned page No. 1107, in  
 book No. 1

Eleanor L. Vaughn, by Betty Bell,  
 County Official deputy

Cross Index No. J-11 T. 36N R. 27W PMM

Sec. 9



• - corner this sheet