ce found, note discrepancies in the record, state method of

3. Description of monument and accessories set to perpetuate the corner position.

- Sketch for corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 4 corner between Secs 4 & 5 T. 36 N R. 27W P.M.M. Lincoln

Record: Set a limestone 20×12×5 ins. 15ins. in ground for 1/4 corner marked 1/4 from which a pine 9" dian bears N.680 W. 1881KS. Dug. pits for other RMs.

Found a loose Stone fitting description near fence corner. Accepted fence corner - set brass cap at the Cence corner and set stone alongside

See Cof S. No. 541 for adjacent corners

book No. .

	CERTIFICATION
Later 1/4 Res	certify the information shown herein is true and correct.
5 4 East to repar 1978 2980ES	Signature Ground Party Chief I. D. K. Macca Lack certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: D-G-B Reg. No. 2289 F S
SKETCH OF CORNER	Employer:
Office of Clerk and Recorder, County of	This "corner day of 198%