Description of evidence found, note discrepancies in the record, state method of est.

- 3. Description of monument and accessories set to perpetuate the corner position.
  4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
   Fill in Cross Index & Secitor Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner 14 con between Sec. 5 & 6 T. 36N R. 27W P.M.M. Lincoln

Record:

Set a sandstone 18x8x8" 12" in the ground marked 14 on West face from which:

a pine 16" diam. bears N.24°30'E. 1391ks.

a pine 20" diami bears 10.50°30' W 50 lks.

Found original stone and 1 BT Set brass cap and buried stone alongside See C. of S. No. 541 for Section Subdivision.

CERTIFICATION certify the information shown herein is true and correct. rertify that this Corner Record correctly represents work performed 7-6-81 Reg. No. 2289 F.S.

SKETCH OF CORNER	Employer:	
Office of Clerk and Recorder, County of Lincoln	<b>70</b> -1-46	Sec. 6
Office of Clerk and Recorder, County of		
record" was filed for record on the	day of 198%,	<del></del>
was noted on the cross-index plat and is assigned page No.	150 , in	F-+-+-+-
book No/ Letense L. Vans	my by Betty Bell	
County	ificial aleputy	
Cross Index No	_ т. <u>36N</u> г. <u>37W</u> <sub>РММ</sub>	<ul><li>corner this sheet</li></ul>