

INSTRUCTIONS

1. Original and/or sufficient record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner $\frac{1}{4}$ cor. between Sec. 6 & 7 T. 36N R. 27W P.M.M. Lincoln County

Record:

Set a limestone $20 \times 20 \times 5$ ins. 15 ins. in the ground for $\frac{1}{4}$ Sec. Cor. marked $\frac{1}{4}S$ on N face from which:


a pine 8" diam. bears N. 35° W. 851 ks

a pine 9" diam. bears S. 41° E. 321 ks

Found stone as described and both BT stumps

Set brass cap and buried stone alongside

See C. of S. No. 541 for adjacent corners



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt
certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal


Date: 7-6-81 Reg. No. 2289ES

Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 17th July day of 1981, was noted on the cross-index plat and is assigned page No. 1153 in book No. 1

Cross Index No. E-3 T. 36N R. 27W P.M.M.

Sec. 6



• - corner this sheet