Original and/or subseque cord used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing in

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

Corner 1/4 corner between Sec 2211 T. 360 R. 27W P.M.M. Lincoln Record: Set a sandstone 20x8x6" 15" in the ground marked Yaon D. face.

Dug pits for Rms.

See C.of. 5. No 800 for adjacent corners. Set brass cap by single proportion

PK. Nocil Set brass cap Brass 2630.61 5261.22



certify the information shown herein is true and correct.

certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)


Signature of Surveyor & Seal

Date: 7-10-81 Reg. No. 5989ES

Office of Clerk and Recorder, County of Lincoln _____. This "corner record" was filed for record on the Jebruary 17th ___ day of 1947 book No. 🚣

Eleanor L. Burgher by Betty L. Conces County Official deputy

E-19 T. 360 H. 27W PMM



corner this sheet