	181.27 feet south of the corner.
II.	Found a 4 1/2 in. x 4 1/2 in. concrete post, firmly set, 5 ins. above ground with a 3 1/2 in. diam. Army Corp of Engineers brass cap marked as shown, from which:
	A fir, 11 ins. diam, bears \$76°W, 67.6 ft. dist., mkd. with a healed face.
	Painted red the scribed face and a red band around the bearing trees. Attached Land Survey Monument signs.
	Date of Fieldwork: 8/29/2006 Survey crew: Steve Boyer Magnetic declination: 20° East assumed Equipment used: Hand compass and loggers tape U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293—6211
	CERTIFICATION
	steven A. Boyer 9750LS certify the information shown herein is true and correct.
	Signature Ground Party Chief Steven A. Boyer certify that this Corner Record correctly represents working performed by the or under my direction in incomplificate with the "Corner Record and "(70.22-101) at Baq." (10.23-101) Signature of Surveyor & Seal TVEN A.
SKETCH	Date: 11/06/2006 Reg. No. 9750LS BOYER H OF CORNER NOT TO SCALE Employer: U. S. Forest Service OF CORNER
Offic	ce of Clerk and Recorder, County of Lincoln This "corner Sec. 39
	199626 BOOK: CCR CCER'S PAGE: 10960 Pages: 1
	STATE OF MONTANA LINCOLN COUNTY RECORDED: 12/13/2006 12:40 KOI: CCER'S
	CORAL M. CUMMINGS CLERK AND RECORDER
	TO: US FOREST SERVICE , Standard
	, <u>[;;;;;;;;;;;</u>

_т. <u>36N. r. 28W.</u> р.м., мт

corner this sheet

CERTIFIED CORNER RECORDATION

Record: 1903 Subdivision and Meander lines of T36N, R28W, by Peter M. Cardell and Abraham L. Rinearson and Gordon G. Smith: Set a stone for cor. of secs. 28, 29, 32 and 33 and four bearing

1972 U. S. Army Corp of Engineers Libby Dam—Lake Koocanusa Project, District File No. E 53—1—154, Sheet 28 of 37: Found a stone, BT and 2 stumps. Set a standard U.S.C.E. concrete monument

T. 36 N. R. 28 W. P.M.M. LINCOLN County

S29 S28 Corner SOUTH WC S32 S33

Cross Index No. SOUTH WC

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

trees.