
CERTIFIED CORNER RECORDATION

Corner COE 3402-1-7 Sec 11 T. 36N R. 28W P.M.M. Lincoln County


- 1. Libby Dam Lake Kookanusa Cadastral 1972 map
- 2. Found, 3" Corps of Engineers Brass Cap in 4" concrete, stamped as shown.
- 3. Painted red bands around BTs and attached LSM and BT signs.

Established:

A 7 ins. Douglas Fir bears N88°W, 16.9 ft. distant, scribed "3402—1—7 BT" A 6 ins. Douglas Fir bears N24°W, 11.5 ft. distant, scribed "3402—1—7 BT" Steel posts with PB & LSM decals, bear North and West, 2.0 ft. distant.



MAGNETIC DECLINATION - 16' EAST



Office of Clerk and Recorder, Country Incoln This "corner	
RECORDED: 01/27/2010 3:50 KOI: CCGR'8	
book No To: FILED ,	
G-H/19-20 Cross Index No	_
Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors	

corner this sheet

Sec. 11