CERTIFIED CORNER RECORDATION

Corner <u>COE 3402 1-5 Sec 11</u> T. <u>36N</u> R. <u>28W</u> P.M.M. <u>Lincoln</u> County

- 1. Libby Dam Lake Kookanusa Cadastral 1972 map
- 2. Found, 3" Corps of Engineers Brass Cap in 4" concrete, stamped as shown.
- 3. Painted red bands around BTs and attached LSM and BT signs.


Established:

An 11 ins. Douglas Fir bears S68'W, 181.2 ft. distant, scribed "3402-1-5 BT" An 8 ins. Douglas Fir bears N82W, 175.6 ft. distant, scribed "3402-1-5 BT" Steel posts with PB & LSM decals, bear North and Southwest, 2.0 ft. distant.

> ORPS OF ENGINEER S. PROJ. BNOR YEAR 1972 GENCY

MAGNETIC DECLINATION - 16' EAST





ERICH SCHRACK ได้ "เราเล่น Employer: GLAHE &

SKETCH OF CORNER Lincoln .. This "corner Office of Clerk and Recorder, County of _ 224176 BOOK: CCR CCER'S PAGE: 11410 Pages: 1 Sec. 11 record" was filed for record a state of montana lincoln county RECORDED: 01/27/2010 3:52 KOI: CCER'S was noted on the cross-inde: TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 book No. _ TO: FILED , Cross Index No. <u>H-19 T. 36N</u> R.

Adapted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet