
CERTIFIED CORNER RECORDATION

Corner COE 3123-2 Sec 15 T. 36N R. 28W P.M.M. Lincoln County

- 1. Libby Dam Lake Kookanusa Cadastral 1972 map
- 2. Found 3½" Corps of Engineers Brass Cap in 4" concrete stamped as shown.
- 3. Painted red bands around BTs and attached LSM and BT signs.

Established:

An 11 ins. Douglas Fir bears S37*W, 16.2 ft. distant, scribed "3123—2 BT" An 11 ins. Douglas Fir bears N45*W, 6.0 ft. distant, scribed "3123—2 BT" Steel posts with LSM and PB signs, bear NE and S, 2 ft. dist.



corner this sheet

MAGNETIC DECLINATION - 16' EAST

