
CERTIFIED CORNER RECORDATION

Corner COE 2905-2 Sec 22 T. 36N R. 28W P.M.M. Lincoln County


- 1. Libby Dam Lake Kookanusa Cadastral 1972 map
- 2. Found 3½" Corps of Engineers Brass Cap in 4" concrete stamped as shown.
- 3. Painted red bands around BTs and attached LSM and BT signs.

Established:

A 14 ins. Douglas Fir bears S51°W, 48.5 ft. distant, scribed "2905—2 BT" A 10 ins. Douglas Fir bears N21°W, 56.7 ft. distant, scribed "2905—2 BT" Steel posts with PB & LSM sign bear South and Northeast, 2.0 ft. distant.



MAGNETIC DECLINATION - 16' EAST




ERICH SCHRAC Employer: GLAHE &

SKETCH OF CORNER

Lincoln _. This "corner Office of Clerk and Recorder, County of __ PAGE: 11423 Pages: 1 record" was filed for recor 224189 BOOK: CCR CCER'S STATE OF MONTANA LINCOLN COUNTY was noted on the cross-i RECORDED: 01/27/2010 4:05 KOI: CCER'S TAMMY D. LAUER CLERK AND RECORDER book No. FEE: \$0.00 TO: FILED , Cross Index No. 0-P/14 T. 36N R. 28W PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet