INSTRUCTIONS

 Original and/or su
 Description of evid. nt record used to evaluate the corner position, lound, note discrepancies in the record, state method of ea

Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

CE-1/16Sec. 23 T. 36N R. 28W Corner_ __ P.M.M. __ Lincoln _County

I. None

- Found 1" pipe set by D.K. Marquardt, E.S. 2989, per Certificate of Survey No. 118
- III. Drove a 3/4" x 24" rod into ground with 3-1/4" alum. cap for true corner position.


1" pipe bears S.02020'W.. 0.82'

Established BT's as follows:

6" pine bears S.64°E., 23.7', scribed CE-1/16 S23 BT 6" pine bears S.75°W., 27.3' scribed CE-1/16 S23 BT

Posted BT, Attention, and Land Monument signs; painted blazes red; drove steel post in ground along side corner monument.

For monument location, see the Certificate of Survey on file.



, ·.	CERTIFICATION
	l,
1' PIPE 0 23.7' 16" PINE D.82' SKETCH OF CORNER	Signature Ground Party Chief 1. He Gene Warren certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-10), et seq., M.D.A.) ### Line Warren Signature of Surveyor & Scal Date: 11-85 Reg. No. 27348 Employer: ROCKY=MOUNTAIN-SURVEYORS
Office of Clerk and Recorder, County of	