

INSTRUCTIONS

1. Original and/or substituted record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

. CERTIFIED CORNER RECORDATION

Corner Sec. Cor. 13, 14, 23 & 24 T. 37N R. 27W P.M.M. Lincoln County


Record:

Set a sandstone 20x8x4 ins. 15ins. in the ground marked with 3 notches on S & 1 notch on E edge

Dug pits for RMs.

Found BLM brass cap.

See C. of S. No. 675 for adjacent corners



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

D. K. Maguardt

I certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

D. K. Maguardt
Signature of Surveyor & Seal

Date 7-8-81 Reg. No. 2289ES


Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 17th July day of 1981 was noted on the cross-index plat and is assigned page No. 1117, in book No. 1

Charles L. Vaughn, Jr.
County Official

Cross Index No. D-21 T. 37N R. 27W P.M.M.

Sec. 14



• corner this sheet