INSTRUCTIONS

Description of evidence found, note discrepancies in the record, state method of establis

- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- topography tres, position was excessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 14 corner between Sec 33 & 34 T. 3710 R. arw P.M.M. Lincoln

Record:

Set a sandstone 16x8x6" 11" in the ground for 1/4 Sec. Cor. marked 1/4 on West face

loose stone 1' from fence Corneraccepted fence corner as best


Set brass cap at fence corner and buried stone alongside

See c. of S. No. 541 for adjacent corners

nail in 30 pine stump certify the information shown herein is true and correct. 10.85 18" pine I. D. K. Manquard certify that this Corner Record correctly represents work performed <u>ე. გ7° ഡ</u> me or under by direction in compliance with the condution Act" (70-22-101, et seq., M.D.A.) Elia Guaras Signature of Surveyor & Sept Date: <u>7-6-81</u> Employer: **SKETCH OF CORNER** Sec. Office of Clerk and Recorder, County of

X-13 T. 37N R. 27W PMM

record" was filed for record on the day of 1959, was noted on the cross-index plat and is assigned page No. book No. _ County Official



corner this sheet