
## INSTRUCTIONS



Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography tles, position of accessories, etc.


  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner Sec. Coc. 27, 28, 33 & 34 T. 37 N R. 27W P.M.M. Lincoln County Record: sandstone 20x8x6" 15" in the ground marked with edges from which! 3 notches on E 28" dia bears N. 53º 15' E. 951Ks 26" dia. bears 5.35° 30' E. 19 1Ks 25" dia. bears 5.27°W. 571Ks 7,2 14" dia. bears N. 52°30'W. 291Ks. 7,2

found stone ¿ four old BT s cap and buried stone alongside brass C. of S. No 541 for adjacent corners



 $\sqrt{13}$ 

Deputy

County Official