CERTIFICATE OF SURVEY "RETRACEMENT" S1/2 NE1/4, SE1/4 SEC. 22, T.29N., R.29W., P.M., MT. LINCOLN COUNTY, MONTANA FOR: PLUM CREEK TIMBER CO. DATE: MAY, 2012 PCTC (N 89°57' E 39.87 Chs. = 2631.42') (N 89°57' E 39.87 Chs. = 2631.42') $N\frac{1}{4}$ N 89°58'55" W 2620.66' N 89°56'09" W 2640.44' S15 S14 S16 S15 1310.33' 1310.33' 1320.22 1320.22 S21 S22 **S22** S22 S23 NE 1/4 LEGAL DESCRIPTION An aliquot tract of land lying northeasterly from Libby, Montana, Lincoln County and more particularly described as: South Half Northeast Quarter (S1/2NE1/4), Southeast Quarter (SE1/4), Section 22, T.29N., R.29W., P.M., MT., Containing 239.85 acres. Subject to and together with all appurtenant easements of record. LAND SURVEYORS NOTE Refer to Certified Corner Recordation forms filed with the Lincoln County Clerk and Recorder's office for specific corner information. CN 1/16 $N\frac{1}{16}$ S 89°58'10" E 2636.06' 1318.03' 1318.03' 1314.27' 1314.27' S 89°59'29" E ^{2628.54} PURPOSE OF SURVEY The purpose is the resurvey of record parcels of land; establish corners, and mark property boundaries. Therefore no division of land is hereby created and is exempt from review as a subdivision, pursuant to 76-3-404, MCA. NE 1/4 HISTORY OF SURVEY 1893, GLO Survey of Township Boundary, Paul Bickel 1898, GLO Survey of Township Subdivisions, Paul Bickel 1976, BLM Remonumentation of original corners, D. Lindenberg, 2008, COS No. 3899, Retracement, A. F. Hughes 7322LS 2008, Remonumentation of Corners, A. F Hughes 7322LS $W\frac{1}{4}$ 88 U METHOD OF SURVEY E14. 1318.22' 1315.85' 1315.85' A total station and GPS system with data collector were used with closed traverse S23 60 0 procedures to tie the previously set controlling corners by Kelly Rooney, May, 2012. S21 S22 S22 N 89°59'56" E 2636.44 N 89°59'56" E 2631.70' Õ L BASIS OF BEARING The basis of bearing for this survey is derived from a survey grade Trimble R8 GNSS GRAPHIC SCALE GPS system using the WGS 84 ellipsoid with a local coordinate datum. Mr. LAND SURVEYOR'S CERTIFICATION I hereby certify that I am a Registered Land Surveyor in the State of Montana, (IN FEET) that the survey shown on this Certificate of Survey has been prepared under 1 inch = 400 ft.my supervision and in accordance with the Montana Code Annotated. Sections 76-3-101 through 76-3-625, and the Lincoln County LEGEND Regulations adopted pursuant thereto. 2643.68 2643.65 SECTION CORNER, A 2 1/2 INCH DIAMETER IRON PIPE WITH 3 1/4 INCH DIAMETER BRASS CAP MARKED BLM 1976 1314.40' 1314.40' **EXAMINING LAND SURVEYOR'S CERTIFICATION** QUARTER CORNER, A 2 1/2 INCH DIAMETER IRON PIPE WITH 3 1/4 INCH DIAMETER BRASS CAP MARKED BLM 1976 S 89°50'38" W | 2628.80' Examined this 24 Th day of MAY S 00°01 SET 5/8 INCH DIAMETER REBAR WITH A 3 1/4 INCH DIAMETER USFS ALUMINUM CAP MARKED HUGHES, 7322LS Ronald A. Pearson, 9008LS Lincoln County Examining Land Surveyor FOUND 31/4 INCH DIAMETER ALUMINUM CAP MARKED HUGHES, 7322LS PROPERTY LINE MARKED AND POSTED THIS SURVEY CLERK AND RECORDER'S CERTIFICATION --- SECTION SUBDIVISION LINE State of Montana, County of Lincoln, filed this GLO RECORD () RECORD, CERTIFICATE OF SURVEY NO. 3899 COMPUTED POINT, NOT FOUND OR SET

S22

1312.95'

N 89°41'19" E 2625.90' (N 89°52' E 40.045 Chs. = 2642.97') **S22**

S27

1312.95

S23

S26

CERTIFICATE OF SURVEY No

Doc 239096