CERTIFICATE OF SURVEY

"BOUNDARY LINE ADJUSTMENT' W1/2 W1/2, SE1/4 SW1/4, SECTION 8, T.30N., R.31W., P.M., MT. LINCOLN COUNTY, MONTANA

VICINITY DIAGRAM

SECTION 8

PARCEL

54

W1/2 SW1/4 Plum Creek Timberlands LP FOR: DAVE KNELLER DATE: OCTOBER 2012 N89°34'08"E 2660.34 {N89°31'17"E 2660.56} (N89°31'E 40.31 Chs = 2660.46) 4 N89°33'41"E 1330.31 [N89°30'39"E 1330.42] N 89°34'22" E 1330.03

LEGAL DESCRIPTION, PARCEL "A1" An aliquot parcel of land, southwesterly from Libby, Montana, Lincoln County and the W1/2 NW1/4, NW1/4 SW1/4.

Section 8, T.30N., R.31W., P.M., MT. more particularly described as follows: Commencing at the SW 1/16th Corner said Section, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS, also being the TRUE POINT OF BEGINNING;

Thence along east-west subdivision line, S89*40'50"W, 1326.85 feet to the S 1/16th corner between Sections 7 and 8, a set 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the Section Line between said Sections N00'18'39 , 1323.85 feet to the 1/4 Corner between said Sections, a 2 1/2 inch diameter iron pipe with BLM brass cap; Thence along said Section Line N00°05'49"E, 2637.06 feet to the Section Corner of Sections 6, 5, 7, and 8, a 2 1/2 inch diameter iron pipe with BLM brass cap; Thence along Section Line of Sections 5 and 8 N89°34'22"E, 1330.03 feet to the W 1/16th Corner of said Sections, a 5/8 inch diameter iron rebar with plastic cap

marked MDL, 4232S; Thence along north-south subdivision line, S00°10'46"W, 2638.35 feet to the C-W 1/16th Corner, Section 8, a 5/8 inch diameter iron rebar with plastic cap marked MDL, 4232S; Thence along said subdivision line, S00°16'59"W, 1325.08 feet to the SW 1/16th Corner and the TRUE POINT OF BEGINNING, containing 120.75 acres. Subject to and together with all appurtenant easements of record.

LEGAL DESCRIPTION, PARCEL "B1"

An aliquot parcel of land, southwesterly from Libby, Montana, Lincoln County and the SE1/4 SW1/4, SW1/4 SW1/4, Section 8, T.30N., R.31W., P.M.,MT. more particularly described as follows: Commencing at the SW 1/16th Corner said Section, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS, also being the TRUE POINT OF BEGINNING;

Thence along the east-west midline of SW1/4, Section 8, S89°40'50"W, 1326.85 feet to S 1/16th Corner between Sections 7 and 8, a set 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the Section Line between said Sections S00°18'39"W, 1323.85 feet to the Section Corner of Sections 7, 8, 17, and 18, a 2 1/2 inch diameter iron pipe with BLM brass cap; Thence along Section Line of Sections 8 and 17 N89'44'30"E, 1327.48 feet to the W 1/16th Corner between said Sections, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the Section Line between said Sections N89'44'30"E, 1327.48 feet to the 1/4 Corner between Sections 8 and 17, a 2 1/2 inch diameter iron pipe with BLM brass cap; Thence along the south-north midline of Section 8 N00'15'15"E, 1326.67 feet to the C-S 1/16th Corner, said Section, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the east-west midline of SW1/4, said Section, S89'40'50"W. 1326.83 feet to the SW 1/16th Corner said Section and the TRUE POINT OF BEGINNING, containing 80.75

An aliquot parcel of land, southwesterly from Libby, Montana, Lincoln County and the SW1/4 SW1/4, Section 8, T.30N., Commencing at the SW 1/16th Corner said Section, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES,

Thence along the east—west midline of SW1/4, Section 8, S89°40'50"W, 1326.85 feet to S 1/16th Corner between Sections 7 and 8, a set 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the Section Line between said Sections S00'18'39"W, 1323.85 feet to the Section Corner of Sections 7, 8, 17, and 18, a 2 1/2 inch diameter iron pipe with BLM brass cap; Thence along Section Line of Sections 8 and 17 N89'44'30"E, 1327.48 feet to the W 1/16th Corner between said Sections, a 5/8 inch diameter iron rebar with plastic cap marked HUGHES, 7322LS; Thence along the south-north midline of SW 1/4 said Section N00'16'59"E, 1325.26 feet to the SW 1/16th Corner and the TRUE POINT OF BEGINNING, containing 40.35 acres.

HISTORY OF SURVEYS

that is greater than 20 ocres".

ACKNOWLEDGMENT

1978 - BLM Plats, Dependent Resurvey, Shirley B. Hjellum and James S. Pritchard

1986 - COS No. 1534, Parcels in SE1/4 NW1/4, Section 8, Melvin D. Lauteren, 4232S

PURPOSE OF SURVEY AND OWNER'S EXEMPTION CERTIFICATION

I, Dave Kneller, being the record owner, hereby certify that the purpose of this survey

and division of land is the relocation of common boundaries and is therefore exempt from subdivision review pursuant to MCA 76-3-207(1)(a): "divisions made outside

of a platted subdivision for the purpose of relocating common boundary lines between

by the Department of Environment Quality pursuant to MCA 76-4-102(16): "a parcel

The foregoing Certification was subscribed and acknowledged before me, Notary Public

for the State of Montana, County of Sincal by the above named person

on this 29 day of October 20/2. In witness whereof, I have hereunto set

__My Commission expires: Dec 1, 2013

my hand and affixed my notorial seal.

Notary Public for the State of Montana

adjoining properties". I further certify that Parcel "A1" and "B1" are exempt from review

2007 - COS No. 3753, Boundary Retracement of NE1/4 NW1/4, SE1/4 NW1/4, Section 8, James R. Staples, 9958LS

2011 - COS No. 4103 RB, Boundary Line Adjustment of W1/2 W1/2, SE1/4 SW1/4, Section 8, Alvah F. Hughes, 7322LS

METHOD OF SURVEY

A Trimble R8 GNSS system was used with RTK radial procedures to tie the previously set controlling corners and road alignments by Kelly Rooney, July 2010

BASIS OF BEARING

The basis of bearing for this survey is S89°44'30"W derived from a Trimble R8 GNSS system using local control between the southwest Section corner, Section 8 and the south Quarter corner, Section 8, both being a 2 1/2 inch diameter iron pipe with BLM brass cap dated 1962.

> ALVAH F. HUGHES

7322 LS

LAND SURVEYOR'S CERTIFICATION

I hereby certify that I am a Registered Land Surveyor in the State of Montana, that the survey shown on this "Certificate of Survey" has been prepared under my supervision and in accordance with Montana Code Annotated, Sections 76-3-101 through 76-3-625 and the Lincoln County regulations adopted pursuant thereto.

EXAMINING LAND SURVEYOR'S CERTIFICATION

Examined this 25 day of OCTOBER 2012 A.D.

VZRID.


County Examining Land Surveyor, Ronald A. Pearson, PLS, 9008LS

LINCOLN COUNTY TREASURER'S CERTIFICATION

CLERK AND RECORDER'S CERTIFICATION

CERTIFICATE OF SURVEY No 4200 RB

DOCUMENT No # 244309



E1/2 SE1/4 NW1/4

NE1/4 NW1/4

Randy & Deloris Augustine

W1/2 SE1/4 NW1/4

Ralph Jr. & Rita L. Heinert

W1/2 NW1/4

PARCEL "A1"

120.75 Acres