CERTIFIED CORNER RECORDATION

Corner WC CNNWSE 1/256 S4 T. 25 N. R. 28 W. P.M.M. Lincoln County

- I. Record: None
- II. Found: No record monuments found.
- III. Perpetuation: The corner point determined by survey falls in a boggy swamp area, we set a witness corner to it, a 5/8 ins. diam. steel rebar 30 ins. long, 29 ins. in the ground, with a 3 1/4 ins. diam. Aluminum cap marked as shown below from which:

A Spruce, 9 ins. diam., bears S55°E, 7.30 ft. dist. scribed WC CNNWSE 1/256 S4 BT. A Spruce, 9 ins. diam., bears N27°W, 23.80 ft. dist. scribed WC CNNWSE 1/256 S4 BT.

Set a steel post on line 1.00 ft. West of set monument with attached Survey Monument and Property Line stickers.

Magnetic declination: 18° East

Equipment used: Hand compass and loggers tape

T25N R28W


50 FT. WC

CNNWSE
1/256
S4

7322 LS
2011

Note: See Certificate of Survey No. 4121 Lincoln County Records for additional survey information.

Kootenai Surveyors Inc., 314 California Av., Libby, MT. 59923 (406) 293-4354



Office of Clerk and Record	er, County of Lincoln	This "corner
record" was filed for reco	236195 BOOK: CCR CCE STATE OF MONTANA LINCOLN C	
was noted on the cross-	RECORDED: 12/01/2011 1:50) KOI: CCER'S
book No.	TAMMY D. LAUER CLERK AND FEE: \$0.00 BY: TO: KOOTEMAI SURVEYORS INC. P	RECORDER Learne Seunes deputy 1.0.BOX 393, LIBBY, MT 59923
Cross Index No. T		т 25N в 28W рм мт

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• corner this sheet

Sec.