

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography lines, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner North $\frac{1}{4}$ Sec. 13 T.25N R.29W P.M.M. Lincoln County

Remonumentation Record:

Set an iron post with brass cap from which:
 A 14" diam. fir bears N. $14\frac{1}{2}^{\circ}$ E. 91ks.
 A 16" diam. fir bears S. 34° E. 151ks.

Found BLM brass cap per record.

See CofS. No. 1088 for adjacent corners.



SKETCH OF CORNER

CERTIFICATION

I certify the information shown herein is true and correct.

Signature of Land Party in Interest

Dawn McAlister

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.L.A.)

Signature of Surveyor & Seal

Dawn McAlister Reg. No. 73285


Date 1/6/82 Employer Marquardt Surveying

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the January 5th day of 1982. was noted on the cross-index plat and is assigned page No. 2143, in book No. .

Janet B.F. Siegel by Betty L. Concea
County Official Deputy

Cross Index No. J-23 T.25N R.29W P.M.M.

Sec. 13



• corner this sheet