2. Description of evidence found, note discrepancies in the record, state method o

3. Description of monument and accessories set to perpetuate the corner position

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, lopography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

5. Certification must be signed and sealed by Registered La 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION


Corner INTERSECTION POINT <u>†</u> T. <u>25n</u> **R**30W P.M.M. LINCOLN LINE 2-3 ROSCOE LODE LINE 3-4 DALY LODE

RECORD: NOVEMBER 1918; CORNER 3 DALY; THENCE N29° 52'E 273.0' INTERSECT LINE 2-3 OF THE ROSCOE LODE. CORNER 2 ROSCOE; THENCE NO8°06'W 37.70' INTERSECT LINE 3-4 OF THE DALY LODE, NOTHING SET AT THE INTERSECTION POINT.

FOUND: NOTHING WAS FOUND AT THIS POSITION.

MAINTENANCE: AT THE INTERSECTION POINT SET A STANDARD 34 INCH ALUM. CAP ON A 30 INCH LONG PIPE 26 INCHES INTO THE GROUND AND STAMPED AS SHOWN, FROM WHICH;

A 10 INCH HEMLOCK BEARS N20°W 4.80' AND SCRIBED X BT A 8 INCH HEMLOCK BEARS S50°E 9.10' AND SCRIBED X BT. CORNER 2 ROSCOE LODE BEARS S07°57'09"E 32.65' CORNER 3 DALY LODE BEARS S30°06'W 267.26' SET STEEL POSTS ON THE PROPERTY LINES 3 FEET FROM CORNER. ATTACHED REQUIRED SIGNS AND PAINT TO BEARING TREES.



. This "corner record" was filed for record on the day of 19/8 was noted on the cross-index plat and is assigned page No. book No. County Official Cross Index No. N-12 T. 25N R. 30W PMM

· corner this sheet