INSTRUCTIONS

1. Original and Rosequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner No.2 ROSCOE MS 10206 T. 25N R.30W P.M.M. LINCOLN County

RECORD: NOVEMBER 1918; SET A HEMLOCK POST 6 INCHES SQUARE 47 FEET LONG 18 INCHES IN THE GROUND IN A MOUND OF EARTH, SET NAIL AT CORNER POINT AND SCRIBED 2 R 10206.

A CROSS ON A HEMLOCK TREE 18 INS. IN DIAM. BEARS N65 E 7.0 FEET A CROSS ON A TAMARACK TREE 18 INS. IN DIAM. BEARS S05 E 24.60 FEET, EACH BLAZED AND SCRIBED BT 2 R 10206.

FOUND: ROTTED POST REMAINS IN A LARGE MOUND OF EARTH, FROM WHICH; \overline{A} 26 INCH LARCH BEARS S05°E 25.0 FEET WITH VISIBLE SCRIBING. NO TRUE STUMP HOLE COULD BE FOUND FOR OTHER BEARING TREE.

MAINTENANCE: SET A STANDARD 34 INCH ALUM. CAP ON 30 INCH LONG PIPE 26 INCHES INTO THE GROUND AND STAMPED AS SHOWN. NO NEW BEARING TREES WERE MADE. ATTACHED SIGNS AND PAINT TO ORIGINAL BEARING TREE.



18 DECLINATION

26" Larch

505°€ 25°A+

SKETCH OF CORNER

CERTIFICATION

DAN CROFT

Signature Ground Party Care

t. H. GENE WARREN
cerlify that this Corner Record correctly represents y
by me or under by direction in compliance wite
Recordation Act., (70-22-101, et seq., M. A.)

Signature of Surveyor Sept. 11-30-98 Reg. No. 2734s

_ R. <u>30W__ PMM</u>

Employer: ROCKY MOUNTAIN SURVEYORS

<u>Se</u>c. 16

Cross Index No. N-12

WARKEN 2734 S

corner this sheet