

INSTRUCTIONS

Q:CO-STD/152
Created 4/8/92

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 1 Basil MS 6189 & No. 3 Silver Star MS 6193 & T. 25 N. R. 30 W. P.M.M. LINCOLN County
No. 1 Galena MS 6194

RECORD:

MS NO. 6189 Basil Corner No. 1

I commenced this survey at Cor. No. 1, identical with S.W. location corner, where I set a post, 4 1/2 ins. square, 5 ft. long, 2 ft. deep, marked 1-6189, for Cor. No. 1, and raised a mound of stone and earth around post.

The U.S.L.M. No. 6185, bears S.30°43'E., 1691.3 ft.

Mouth of tunnel No. 2, 5x7 ft., 100 ft. long, bears, bears N.80°E., 200 ft. Course of tunnel S.80°W.

MS NO. 6193 Silver Star Corner No. 3

1500 N.W. location corner and Cor. No. 1 of Sur. 6189, a post, 4 1/2 ins. square, 5 ft. long, 2 ft. deep, marked 1-6189, I marked 3-6193, for Cor. No. 3 of this survey, there is a mound of earth and stone around post.

A blazed hemlock tree, 8 ins. diam., marked B.T. 3-6193, bears S.10°15'W., 11 ft.

MS NO. 6194 Galena Corner No. 1

I commenced this survey at Cor. No. 1, identical with N.E. location corner and Cor. No. 1 of Sur. 6189 and Cor. No. 3 of Sur. 6193 with, where is set a post, 4 1/2 ins. square, 5 ft. long, 2 ft. deep, marked 1-6189, 3-6193, I marked 1-6194, for Cor. No. 1 of this survey, there is a mound of stone and earth around post.

The U.S.L.M. No. 6185, bears S.30°43'W., 1691.3 ft.

A blazed hemlock tree, 8 ins. diam., marked B.T. 1-6194, bears S.10°15'W., 11 ft.

FOUND:

No remaining evidence of the post, stone mound or original hemlock tree remains. Unable to determine location of Tunnel No. 2.

TO PERPETUATE:

At record position, set a 5/8" x 24" rebar flush with the surface, with a USFS 3-1/4" aluminum cap, marked as shown below.



From which new trees:

A hemlock, 12" in diam., bears N.13°W., 30.90', blazed and scribed "1 MS 6189 BT".

A hemlock, 27" in diam., bears N.26°E., 50.50', blazed and scribed "1 MS 6189 BT".

Place a "Land Survey Monument" (54-9), and a "Bearing Tree" (54-3) sign on the bearing trees. Painted all blazes red, and a 6" red band above the "Bearing Tree" signs. Placed 6" steel posts on property line, 50' +/- from the corner, with "Land Survey Marker" (54-9), and "Property Boundary" (54-2) decals.

See Certificate of Survey, recorded in Lincoln County



SKETCH OF CORNER

CERTIFICATION

I, Kevin Cassidy
certify the information shown herein is true and correct.

Kevin Cassidy
Signature Ground Party Chief

I, R.A. Ainsworth
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

R.A. Ainsworth
Signature of Surveyor & Seal

Date: 11/00 Reg. No. 2923S

Employer: Professional Consultants, Inc.

Sec. 7

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on Jan 10, 2001 was noted on the cross-index plat and is assigned page No. 10467, in book No. Corral M. Cunningham By DB

County Official

