

INSTRUCTIONS

Q:CO-STD/152  
Created 4/8/92

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 1 Fides MS 6187 T. 25 N. R. 30 W. P.M.M. LINCOLN County  
No. 1 Silver Bow MS 6188

RECORD:

MS NO. 6187 Fides, Robert C. Williams, U.S. Deputy Mineral Surveyor, 1901  
Corner No. 1

I commenced this survey at Cor. No. 1, identical with N.W. location corner, set a post, 4 1/2 ins. square, 5 ft. long, 2 ft. deep, marked 1-6187, for Cor. No. 1, and raised a mound of stone and earth around post.  
U.S.L.M. No. 6185 bears N.27°52'E., 332.2

MS NO. 6188 Silver Bow, Robert C. Williams, U.S. Deputy Mineral Surveyor, 1901  
Corner No. 1

I commenced this survey at Cor. No. 1, identical with S.W. location corner and Cor. No. 1 of Sur. No. 6187, where is set a post, 4 1/2 ins. square, 5 ft. long, 2 ft. deep, marked 1-6187, I marked it 1-6188 for Cor. No. 1, and raised a mound of stone and earth around post.  
U.S.L.M. No. 6185 bears N.27°52'E., 332.2

FOUND:

Found a mound of stones 4' base, 1.3' high.

TO PERPETUATE:


At accepted mound of stone position, set a 5/8" x 24" REBAR, with a USFS 3-1/4" aluminum cap, 12" in the ground with a 3' x 1' mound of stones to cap, marked as shown below.


From which new trees:

- A lodgepole pine, 7" in diam., bears S.89°W., 12.81', blazes and scribed "1 MS 6188 BT".
- A lodgepole pine, 9" in diam., bears S.09°W., 17.3', blazed and scribed "1 MS 6187 BT".

Place a "Land Survey Monument" (54-9), and a "Bearing Tree" (54-3) sign on the bearing trees. Painted all blazes red, and a 6" red band above the "Bearing Tree" signs. Placed 6' steel post at the corner, with "Land Survey Marker" (54-9).

See Certificate of Survey, recorded in Lincoln County





**CERTIFICATION**

I, Matt Jacobson  
certify the information shown herein is true and correct.

*Matt Jacobson*  
Signature Ground Party Chief

I, R.A. Ainsworth  
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

*R.A. Ainsworth*  
Signature of Surveyor & Seal  
A. AINSWORTH  
Date: 11/00 Reg. No. 2923SS  
Employer: Professional Consultants, Inc.

SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on Jan 10, 2001 was noted on the cross-index plat and is assigned page No. 10483, in book No. \_\_\_\_\_

*Carol M. Cummings*  
County Official
